

Staebel Positioning & Support Wedge User Manual

Product Code: 3689



Thank you for choosing Staebel Positioning & Support Wedge

We aim to ensure you are satisfied with your product in terms of both performance and durability. We therefore kindly ask you to spend a few minutes reading through these user instructions to ensure you can take the best possible care of your product. If you have any questions that are not answered in these user instructions, please contact us at Staebel.

- DO NOT USE in the vicinity of or in contact with fire sources/hot surfaces.
- Position and use the product in a manner that prevents it from becoming trapped or damaged.
NOTE: Be particularly aware of trapping damage when using bed rails.
- Prevent damage to the cover from sharp objects.

CLEANING/DISINFECTION

Foam Core

- The hygiene cover protects the foam core completely, which means cleaning seldom is necessary. If, for any reason, the core needs to be cleaned, use a mild cleaning solution and water (for example spray on). Press out the water carefully.
- Let the foam core dry in a warm, ventilated area, without direct exposure of sunlight. The foam core needs to be completely dry before it is used again.

Cover

- Some surface wrinkling may result from cleaning procedures. This has no adverse effect on the cover properties
- Abrasive cleaning agents should not be used.
- The cover can be tumble dried provided the operator ensures it is removed as soon as all moisture is removed. The cover must not be left sitting on the heated bowl of the dryer when drying is complete.
- Do not iron the cover
- If customers have their own particular cleaning methods that must be used and that are not covered in this article, they should consult with Staebel for further direction.
- The Cover needs to be treated with care when cleaning the surface. Many industrial cleaning agents are extremely harsh on the coating and can cause it to break down. Please refer to the list of cleaning products that have been tested and approved for use on the Cover.
- To avoid premature degradation of the surface coating never use an abrasive cloth, sponge or other similar device on the surface. Carefully follow manufacturer instructions for recommended exposure time of cleaner on surface. Wipe off cleaning product residue with a clean, soft cloth after cleaning and allow the surface to dry completely before use.
- The normal cleaning instructions are to wipe the surface clean with a sponge or cloth with warm soapy water.
- The Cover can be washed in warm soapy water at up to 95°C.
- Do not use solvent on the cover.
- The cover is dry-cleanable with all dry cleaning fluids except trichloroethylene.
- The cover is able to be autoclaved at a temperature of 134°C for 3 minutes. However, care must be taken to first clean the surface with pure water and then to make sure that they are not stacked on top of each other without any air gap separation.

Storage

Store in a cool dry area. Avoid excessive pressure and contact with non-colourfast materials. Make sure the is stored where it will not be exposed to thrusts, hits or other things that can damage it.

WARRANTY

We warrant the product to be free from manufacturing defects for the period of **5 years** (foam core) and **1 year** (cover) from date of purchase. This warranty does not extent those items that may need replacement due to normal wear and tear, or to damaged caused by misuse or accident, for which Staebel or it's distributors cannot be held responsible. If your accessory should need attention due to failure as defined under the warranty above, please contact the distributor from whom you purchased your accessory.